

Site Name	Owner	Location	Lat/Long	Size	Contamination Issues	2008 Planned	2008 Complete	2009 Planned	2009 Complete	2010 Planned	2010 Complete	2011 Planned	2011 Complete	2012 Planned	2012 Complete	2013 Planned	2013 Complete	Suitability for Use	Institutional Controls
Sand Point	KBIC Trust Land	US-41 Baraga	46.7890167 88.458767	45 Acres	Mine scarred land			Revegetation	None	Revegetation								Restricted use due to presence of stamp sands. No groundwater use allowed.	None
Draper Lakeshore	KBIC	619 US-41, Baraga	46.772567 88.4910167	Approximately 1 Acre	Petroleum	Phase II Environmental Site Assessment (ESA)	None	Phase II Environmental Site Assessment (ESA)	Conducted June 23 - August 4, 2009	Groundwater Sampling	None	Groundwater Sampling	Conducted May 24-25, 2011						
Mud Lakes	KBIC Trust Land	Old US-41/Mission Road Baraga	46.82269 88.48384	15 Acres	Hazardous substances	Phase I ESA	Completed March 10, 2008	Phase II ESA	Conducted July 21-22, 2009							Open Dump Clean Up	None		
Johnson Road Dump	KBIC Trust Land	South Johnson Road, L'Anse	46.808983 88.404083	30 Acres	Hazardous substances	Phase I ESA	Completed July 17, 2008	Phase II ESA	Conducted May 27, 2009							Open Dump Clean Up	None		
Power Dam Junkyard	KBIC Trust Land	US-41/Power Dam Road L'Anse	46.739373 88.43246626	28 Acres	Hazardous substances & Petroleum	Phase I ESA Initial Phase II ESA	Draft October 22, 2008 Conducted October 28-30, 2008	Additional Phase II ESA Work	Conducted October 30 & November 9, 2009	Groundwater Sampling	None	Groundwater Sampling	Conducted May 24-25, 2011						
Tailor Road	KBIC Alloted & Trust	Tailor Road, L'Anse	46.7859 88.428383	40 Acres	Hazardous substances	None	None	Phase I ESA & Phase II ESA	Phase I-Draft October 8, 2009 Phase II- November 12, 2009	Additional Phase II ESA	Phase I - January 14, 2010 Asbestos Inspection- August 9, 2010					Open Dump Clean Up	None		
Bear Track	KBIC Alloted & Trust	Bear Track, L'Anse	46.7902 88.41713	80 Acres	Petroleum & Hazardous Substances	None	None	None	None	Phase I ESA & Phase II ESA	Phase I-May 11, 2010 Phase II-June 7, 2010					Open Dump Clean Up	None		
Lindemann Road	KBIC Trust Land	14444 Lindemann Road, Baraga	46.80053 88.4899	0.57 Acres	Hazardous Substances	None	None	Phase I ESA & Phase II ESA	Phase I- August 21, 2009 Phase II- September 16, 2009							Open Dump Clean Up	None		
Ben Road	KBIC Trust Land	Ben Road, Baraga	46.7976 88.4933	5 Acres	Petroleum & Hazardous Substances	None	None	None	None	Phase I ESA	None	Phase I ESA	None	Phase I ESA & Phase II ESA	Phase I-June 28, 2012 Phase II- August 2, 2012	Open Dump Clean Up	None		
Beartown Road #2	KBIC Alloted & Trust	Beartown Road, Baraga	46.8116167 88.5195	10 Acres	Petroleum & Hazardous Substances	None	None	None	None	Phase I ESA	None	Phase I & Phase II ESA	Phase I- May 12, 2011 Phase II- August 17, 2011			Open Dump Clean Up	None		
Assinnins Road	KBIC Trust Land	14791 Assinnins Road, Baraga	46.806 88.472267	15 Acres	Petroleum & Hazardous Substances	None	None	Phase I ESA	None	Phase I & Phase II ESA	Phase I- May 13, 2010 Phase II- August 17, 2010			Additional Phase II ESA Work (tank investigation)	None	Open Dump Clean Up	None		
Rantanen-Herman Trailer	KBIC Trust Land	19851 Herman Road, L'Anse	46.68737861 88.38940287	0.5 Acres	Petroleum & Hazardous Substances	None	None	Phase I ESA	None	Phase II ESA	Phase I - July 9, 2010 Phase II- August 12 2010								
Beartown Road #6	KBIC	Beartown Road, Baraga	46.85173 88.5090167	Part of 82 Acre parcel	Petroleum & Hazardous Substances	None	None	None	None	Phase I ESA & Phase II ESA	Phase I - May 13, 2011 Phase II- no further action					Open Dump Clean Up	None		
Pikes Peak Carcass	KBIC	Pikes Peak Road, L'Anse	46.822067 88.36823	80 Acres	Petroleum & Hazardous Substances	None	None	None	None	Phase I ESA & Phase II ESA	Phase I- September 1, 2010 Phase II- October 20, 2010					Open Dump Clean Up	None		